

eqss™ Gen-3 LMS Telehandler Load Management System

Installation Manual for JCB 540-140



PLEASE NOTE:

Do Not Swap Components between Gen3-LMS kits

When installing multiple Gen3-LMS kits, make sure the serial number on the sticker matches the serial number on the machine.

Failure To Follow Installation Manual Will Void Warranty

Documentation Conventions

The list below highlights important documentation conventions.



Text presented in this manner is intended to provide the user with some general information. The user should ensure information presented in this manner is clearly understood.



Text presented in this manner provides the user with information to assist in completion of the current procedure being explained.



Text presented in this manner indicates that a failure to follow directions could result in damage to equipment, loss of information, bodily harm, or loss of life.

Important Information

Information contained in this publication regarding this device's applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that the application or our equipment meets with your specifications.

EQUIPMENT SAFETY SYSTEMS MAKE NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO, IT'S CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE.

Equipment Safety Systems disclaims all liability arising from this information and its use. Use of Equipment Safety Systems' products as critical components in life support systems is not authorised except with express written approval by Equipment Safety Systems. No licenses are conveyed, implicitly or otherwise, under any Equipment Safety Systems intellectual property rights.

VER: 1706261613 CQ SS 3 of 47

Table of Contents

Tools Required for Installation	5
Installation Index	6
Covers	10
Cable Reeler Installation Cable Reeler Mounting Position	
Pressure Sensor Installation	14
Reverse Camera	18
Forward Camera	19
Signal Light Installation With Windshield Guard Bar Without Windshield Guard Bar	20
Can Pressure Input Module (CPIM)	23
Can Cabin Interface Module (CCIM)	25
External Cable Completion	26
Dashboard Switches	27
Display Installation	28
Machine Connections	30
Finalisation	34
Set Time & Sensor Calibration	38
Appendix A: Attaching Display Connectors	41
Appendix B: Reattach Ferrites	45
Indexes and Tables	46

Tools Required for Installation

The tools required to perform the installation of the TSS are listed below

- Pencil or Texta
- Drill
- Drill bits
 - 。 3.3 mm
 - 4.5 mm
 - 。 5 mm
 - 6.25 mm
 - 6.8 mm
 - 。 8.5 mm
- Centre punch
- · Tap T-Handle
- Taps
 - M6
 - o M7 x 0.75
 - 。 M8
- Drill and tap oil
- Metric Allen keys
- Phillips Head screw driver
- Spanners and sockets
 - 7 mm
 - 10 mm
 - 。 13 mm
- Locktite thread locker
- Side cutters
- Stanely knife
- Crimpers
- Wire strippers
- Hole saw
 - 。 31 mm
 - 。 34 mm

VER: 1706261613 CQ SS 5 of 47

Installation Index

The components and cables of the Gen-3 Telehandler Load Management System are outline in the tables below. The following pages show where the components are installed and the cable routing.

See the appropriate manual section for a detailed installation description for each component.



Refer to this section for any component placement or cable routing issues

Item	Component Description
1	Cable Reeler
2	Main Lift Cylinder Head Pressure Sensor
3	Main Lift Cylinder Rod Pressure Sensor
4	Compensation Pressure Sensors
5	Can Pressure Input Module (CPIM)
6	Forward Camera
7	Reverse Camera
8	Light Tower
9	Can Cabin Interface Module (CCIM)
10	Display Module

Table 1: Component Installation Index

Colour	Cable Description	
Red	Boom Cable	
Dark Green	Main Cylinder Pressure Sensor Cables	
Brown	Compensation Head Pressure Sensor Cable	
Dark Blue	Compensation Rod Pressure Sensor Cable	
Light Blue	Forward Camera Cable	
Violet	Signal Light Cable	
Aqua	Rear Camera Cable	
Dark Purple	CCIM Cable	
Light Green	Cutout Harness	
Light Purple	Height Limiter Cable	
Orange	Display Cable	

Table 2: Cable Installation Index

VER: 1706261613 7 of 47



Illustration 1: Machine Boom

VER: 1706261613 8 of 47




Illustration 2: Machine Chassis

Covers

Remove the following covers before starting the installation

Step	Description	Diagram
1.	Release the dashboard display bolts	
2.	Remove the indicator display behind the steering wheel	

Table 3: Cover removal

Cable Reeler Installation

The cable reeler is used to measure the boom extension to determine the maximum lifting capacity.



A false N07 fault can occur if the boom jumps off the stow switch due to pressurising the hydraulic system and without operating the boom extension control. Ensure the stow switch arm is correctly adjusted to prevent this error.



When mounting the cable anchor ensure it is mounted on the first extendable section not on the last section. If mounted on the last section the cable reeler will be damaged when the boom is extended.

Step	Description	Diagram
1.	Drill and tap holes for the cable reeler according to the mounting diagram on page 13. Mount using the supplied bolts and standoffs.	
2.	Drill and tap an M8 hole for the cable anchor. Ensure the cable anchor is positioned so the cable runs in line with the boom. Mount the cable anchor and attach the cable with the supplied M8 washer and the M8 nylock nut. Note: Ensure the anchor is mounted on the first extendable section not	
	on the last section. If mounted on the last section the cable reeler will be damaged when the boom is	
	extended.	

VER: 1706261613 POPULATION OF 47

Step	Description	Diagram
3.	Drill and tap the M6 holes for the stow switch trigger. Ensure the stow switch arm is pressed/switched when the boom is retracted. Mount the stow switch trigger using the supplied 17mm spacers and M6 bolts.	
4.	Connect the supplied M12 10 metre cable (CB001027) into the cable reeler connection. Cable tie to the hydraulic pipes running underneath the boom then onto the flexible hydraulic hoses down to the chassis. Make sure the cable isn't pinched or stretched when the boom is raised or lowered.	

Table 4: Cable Reeler Installation

Cable Reeler Mounting Position



Illustration 3: Cable Reeler Mounting Position

VER: 1706261613 13 of 47

Pressure Sensor Installation

The hydraulic pressure sensors are used to measure the lifting load of the telehandler.

Main Cylinder Pressure Sensors

IVIG	in Cynnuer Pressure Se	,113013
Step	Description	Diagram
1.	Raise the boom to approximately 40 degrees. Support and secure the boom using an A Frame or similar apparatus. It must support at least 2 tons.	
	Apply the handbrake and insert chock under wheels.	
	Release the blanking cap on the hydraulic port.	
	Removing the blanking cap will release the hydraulic pressure which may result in a spray of oil.	
	Install the supplied pressure sensor and ensure it is tightly sealed.	
2.	Locate the 5/8 BSPP to 3/8 BSPP Hydraulic Tee (Not Supplied, JCB #: 816/90143) and connect to rod pressure sensor connections using the supplied seal as shown.	

Step	Description	Diagram
3.	Install the tee connector and pressure sensor into the rod of the main lift cylinder, where the flexible hose connects to the rod of the lift cylinder. Start the machine, pressurise the boom and check for leaks.	
4.	Connect the supplied M12 4 metre cables (CB001026) into each of the pressure sensors. Cable tie the pressure sensor cables to the flexible hydraulic hoses connected to the main lift cylinder. Make sure the cable isn't pinched or stretched when the boom is raised or lowered.	
	Run the cables towards the cabin and cable tie with the other cables during External Cable Completion on page 26.	
	Ensure the pressure sensors and cables do not collide with the boom and chassis structures and the cables do not stretch or pinch when the boom is raised and lowered.	

Table 5: Pressure Sensor Installation

Compensation Pressure Sensors

mpensation Pressure S	70110010
Description	Diagram
Undo the hydraulic connection for the head compensation where the flexible hydraulic line from the compensation cylinder is connected into the fixed hydraulic pipes on the left side of the boom behind the cabin. Install the supplied tee piece and pressure sensor in line with the hydraulic connection.	
Undo the hydraulic connection for the rod compensation where the flexible hydraulic line from the compensation cylinder is connected into the fixed hydraulic pipes on the right side of the boom behind the engine bay. Install the supplied tee piece and pressure sensor in line with the hydraulic connection. Start the machine, pressurise the	
	Undo the hydraulic connection for the head compensation where the flexible hydraulic line from the compensation cylinder is connected into the fixed hydraulic pipes on the left side of the boom behind the cabin. Install the supplied tee piece and pressure sensor in line with the hydraulic connection. Undo the hydraulic connection for the rod compensation where the flexible hydraulic line from the compensation cylinder is connected into the fixed hydraulic pipes on the right side of the boom behind the engine bay. Install the supplied tee piece and pressure sensor in line with the hydraulic connection.

Step	Description	Diagram
3.	Connect the supplied M12 4 metre cables (CB001026) into each of the pressure sensors.	
	Run the cables along the flexible hydraulic hoses on the boom down to the chassis.	
	Run the cables towards the cabin and cable tie with the other cables during External Cable Completion on page 26.	
	Ensure the pressure sensors and cables do not collide with the boom and chassis structures and the cables do not stretch or pinch when the boom is raised and lowered.	

Table 6: Compensation Pressure Sensor Installation

VER: 1706261613 PQSS 17 of 47

Reverse Camera

The rear camera video is displayed on the screen when the machine is in reverse gear to allow the operator to see behind the telehandler while reversing.

Step	Description	Diagram
1.	Drill a 31mm hole in the location shown. Making sure to leave enough room for a license plate	
	Insert the camera through the hole and adjust the angle using the alignment washers.	
	Connect the camera power and signal connectors to the supplied 5m camera cable (CB001032).	
	Note; The white connector is not used.	
	Secure the camera cable to the	
	license plate light cables.	
	Run the remainder of the cable	
	towards the cabin and cable tie with	
	the other cables during External	
	Cable Completion on page 26.	

Table 7: Reverse Camera Installation



The camera's viewing angle may need to be adjusted once the system is installed and the display is operational.

Forward Camera

The forward camera video is displayed on the screen when the machine is in forward gear to allow the operator to see past the boom to obstructions that would damage the right front tyre.

Step	Description	Diagram
1.	Mount the camera to the side mirror using the p-clips in the location shown.	
2.	Connect the camera power and signal connectors to the supplied 5m camera cable (CB001032). Note; The white connector is not used. Run the cable along the same path as the headlight cable, run it through the headlight post, then under the chassis to the side of the cabin. Cable tie with the signal light cable during External Cable Completion on page 26.	

Table 8: Forward Camera Installation



The camera's viewing angle may need to be adjusted once the system is installed and the display is operational.

VER: 1706261613 PQSS 19 of 47

Signal Light Installation

The signal light warns other workers when the telehandler is lifting loads close to it's maximum capacity.



Ensure the power supply voltage is greater than 13.5V otherwise the signal light may not illuminate correctly.

With Windshield Guard Bar

	iii wiiiasiiicia Saara De	^!
Step	Description	Diagram
1.	Mount the signal light to the top of the front windshield guard on the cabin.	
2.	Run the cable down the side of the windshield and cable tie to the windshield guard bar down towards the chassis.	

Table 9: Signal Light Installation With Windshield Guard Bar

VER: 1706261613 20 of 47

Without Windshield Guard Bar

Step	Description	Diagram
1.	Remove the magnet from the bottom of the signal light mounting bracket and flip the signal light mounting bracket so the mounting holes are on the bottom. Cut and remove 2.6 m of snake tube from the end of the cable starting at the signal light. Drill two M4 holes to mount the signal light bracket to the left headlight support bracket on the roof. Mount using the supplied M4 bolts and nuts.	
2.	Run the cable along the top of the roof to towards the right headlight support bracket. Drill a single M6 hole to mount a metal p-clip. Attach the cable to metal p-clip and secure using the supplied M6 bolt and nut.	
3.	Run the cable down between the edge of the windshield and cabin frame to the base of the windshield. Use a water proof adhesive to ensure the cable will remain within the gap between the edge of the windshield and cabin frame.	

VER: 1706261613 21 of 47

Step	Description	Diagram
4.	Secure the cable to the chassis using a cable tie. Note: Make sure the cable is securely tensioned, so it doesn't move out of the groove between the edge of the windshield and cabin frame.	

Table 10: Signal Light Installation Without Windshield Guard Bar

VER: 1706261613 22 of 47

Can Pressure Input Module (CPIM)

The CPIM is responsible for processing the information sent from the pressure sensors.



Accidentally swapping the pressure sensor connections will not damage system and can be determined if the display is showing a negative load.



Do not plug the pressure sensor cable into the far right side boom cable. This will damage the system.

Step	Description	Diagram
1.	Drill two M8 holes for the CPIM bracket in the side of the chassis in the location shown.	
	Mount using the supplied M8 bolts and nuts.	
2.	Connect the cables for the pressure sensors and boom cable to the CPIM according to the picture shown.	CONSISTENCE OF THE SECOND OF T
	Connect the supplied M12 4 metre cable (CB001026) into the free connection out of the right side of the CPIM for the CCIM cable.	CCIM Boom C Rod M Rod M Head
	Run the CCIM cable towards the hole into the cabin.	

VER: 1706261613 23 of 47

Step	Description	Diagram
3.	Run the height limiter cable from out the left side of the CPIM to the hydraulic block beside the cabin. Connect the tee connector labelled "Raise" from the height limiter cable to boom raise (bottom right) connector on the hydraulic block and the tee connector labelled "Extend" from the height limiter cable to boom extend (second up from bottom right) connector on the hydraulic block.	
	Place a single cable tie to hold each cable position then disconnect the tee's from the raise and extend connectors, otherwise the boom will not move. Complete the cable installation during External Cable Completion on page 26.	Lower Extend Raise

Table 11: Can Pressure Input Module (CPIM) Installation

VER: 1706261613 24 of 47

Can Cabin Interface Module (CCIM)

The CCIM connects the system into the machine electronics.

Step	Description	Diagram
1.	Connect the CCIM and signal light cables to the M12 connectors on the CCIM. Note: It doesn't matter which of the M12 connectors the CCIM and signal light cables are plugged into.	Canara / Power 10
2.	Connect the Power/Camera and IO Harnesses to the bulkhead connectors on the CCIM. Position the CCIM underneath the dashboard using double sided velcro tape. Note: Make sure to leave enough room for the connectors and that the dashboard displays can be reinstalled.	
3.	Install the backup battery behind the indicator display using double sided velcro tape.	

Table 12: CCIM Installation

External Cable Completion

All external cabling is completed in this step.

Step	Description	Diagram
1.	Locate the reverse camera, boom and compensation pressure cables at the rear of the machine and cable tie to the existing snake tube and hydraulic lines running towards and underneath the cabin. Coil up any additional cable and	
	store under the CPIM module and cable tie to the hydraulic lines to keep in place.	View from under the boom towards the rear of the machine
2.	At the front of the machine cable tie the signal light and front camera cables together up to the side of the cabin.	
3.	Run the CCIM, signal light and camera cables through the hole into the cabin.	View from under the boom in the middle of the chassis towards the cabin

Table 13: External Cable Completion

VER: 1706261613 26 of 47

Dashboard Switches

The user input control and override switch are installed in the dashboard.

Step	Description	Diagram
1.	Remove a blanking switch plate from the dashboard and install the override switch.	
2.	Drill a 34 mm hole into the dashboard. Install the user control in the dashboard, aligned so the Enter cap is facing up.	

Table 14: Dashboard Switches Installation

VER: 1706261613 27 of 47

Display Installation

The display shows the current safety status of the telehandler.

Step	Description	Diagram
1.	Position the display bracket in the top right of the dashboard in the approximate location shown. Drill two 7 mm holes to attach the bracket to the dashboard. Secure the bracket to the dashboard using the supplied large washers and nuts	
	Attach the display to the bracket and tighten the grub screw	
2.	Run the 8 pin cable from the CCIM and the 5 pin cable from the user control dial out between the dashboard and cabin plastic mounts and attach to the connectors in the back of the display.	

Table 15: Display Installation



Adjust the display bracket for optimal viewing angle once the display is powered



If the M12 screw lock connectors on the display are over tightened it will twist the connector pins attaching the connector to the PCB. See Appendix A: Attaching Display Connectors on page 41 for the correct method of attaching to the display connectors.



If the clip-on ferrites were removed from the CCIM and user control cables. See Appendix B: Reattach Ferrites and page 45 for the correct reattachment position.

VER: 1706261613 29 of 47

Machine Connections

The following procedures connect the safety systems to the existing electronics in the machine.



Isolate the main battery before starting the machine connections

Step	Description	Diagram
1.	Splice the following wire colours from the stabiliser harness with the 2 pin connector into connector J2 behind the dashboard for the stabiliser signals. Wire Colour J2 Pin (Wire #) Blue 15 (481A)	AND
	Green 16 (410)	
2.	Splice the following wire colours from the machine input harness with the 4 pin connector into the connector for the left steering column switch.	
	Note: Remove the steering wheel height adjustment lever, to move the steering wheel higher, to get better access to the switch connector	
	Wire Colour Wire Number Orange 416F Red 416R	

VER: 1706261613 930 of 47

Step	Description	Diagram
3.	Connect the spade terminals from the machine input harness into the override switch.	
4.	Run the 12 pin tee connector out the hole in the cabin to the chassis. Note: The red and white terminals in the 12 pin tee connectors will need to be removed to fit the cable through the cabin hole. Reconnect the red terminals back into pin 2 and the white terminals back into pin 3 of the tee connector. Connect the 12 pin tee connector	
	Connect the 12 pin tee connector to the joystick connection.	

VER: 1706261613 31 of 47

Step	Description	Diagram
5.	Run the two 2 pin tee connectors on the machine cutout harness through the hole leading outside the cabin, to the hydraulic block located beside the cabin. Connect the tee connector to the boom lower (bottom left) connector on the hydraulic block. Place a single cable tie to hold the cable position then disconnect the tee from the boom lower	
	connector, otherwise the boom will not move.	Lower Extend Raise

VER: 1706261613 32 of 47

Step	Descrip	tion	Diagram
6.	Attach the radio po the radio connector		
	Note: If the radio constalled in the machine the tee connectors power harness and 4 pin radio power collocated under the disaccording to the talk. Wire Colour Black Violet Yellow	hine. Cut off from the radio splice into the onnector ashboard	

Table 16: Machine Connections

VER: 1706261613 33 of 47

Finalisation

This section will complete the final power connections to power the system and finish any additional items.

Step	Description	Diagram
1.	Connect the 4 pin and 12 pin connectors from the machine input harness into the I/O harness.	
2.	Connect the 2 pin and 6 pin connectors from the stabiliser and cutout harnesses to the I/O harness.	
3.	Connect the camera power and signal cables from the front and rear cameras to the power/camera harness connectors. Note: The white connector is not used.	

Step	Description	Diagram
4.	Connect the 3 pin connector into the Power/Camera harness.	
5.	Connect the spade lug on the black wire to the negative (black) battery terminal. Connect the spade lug on the blue wire to the positive (red) battery terminal.	
6.	Coil up the extra cables and store underneath the dashboard cover.	
7.	Reconnect the tee connectors back into the hydraulic block beside the cabin.	

VER: 1706261613 35 of 47

Step	Description	Diagram
8.	Reconnect the main battery from the isolation switch.	
	Turn the machine onto first stage /accessories and ensure the system is activated.	T DOCOURT
9.	Adjust the display bracket for optimal viewing	
	Set the machine into forward gear to activate the forward camera. Adjust the forward camera so the front right wheel is visible.	epa Ger3 Urs
	Set the machine into reverse gear to activate the reverse camera. Adjust the reverse camera so the video is level.	
10.	Operate the boom movement controls to test if a false N07 fault occurs.	
	If a N07 fault does occur, adjust the arm on the stow switch forwards towards the stow switch trigger.	
	Note: The actual switch arm orientation may differ from the picture.	

VER: 1706261613 36 of 47

Step	Description	Diagram
11.	Perform a final check on all the cabling and sensors. Replace all the covers	

Table 17: Finalisation



Complete the system checklist once installation has been completed.

Set Time & Sensor Calibration

Once the installation is complete, the time will need to be set and the sensors will require calibration.



A sensor calibration must be performed once the cable reeler and CPIM have been mounted. If the cable reeler or CPIM have been moved/repositioned a recalibration must be performed

Step	Description	Diagram
1.	Press Enter on the user control dial	Main Menu
	to enter the menu system.	Attachment Selection Menu
	Press the arrow buttons to select	
	System Menu.	System Menu
	Press Enter to select the menu.	
		Exit Menu
2.	Select Advanced Menu	System Menu
۷.	gereet Havaneed Wend	Volume / Brightness
		Status Menu
		Diagnostics Menu
		System Tests
		Advanced Menu
		Return to Main Menu

Step	Description	Diagram
3.	Enter the password	Enter Password
.	(Default Password: 2-8-4)	Number 1 2
		Number 2 8
		Number 3 4
		Submit Password
		Return to System Menu
4.	Select Set Time / Date	Advanced Settings
4,	Select Set Time / Date	Set Time / Date
		Sensor Calibrations
		Change Language
		Change Password
		Return to System Menu
5.	Enter the correct time and date for	Set Time / Date
	your area.	Hour 15
	Press the arrow keys to select a	Minute 54
	time/date parameter	Day 10
	Press Enter and the parameter will	Month 2
	change to red, press the arrow keys	Year 2016
	to change the value and then press the Enter key to store the value.	Region Melbourne
	Note: The hour parameter is in 24 hour clock	
	Repeat for the rest of the time values	

VER: 1706261613 39 of 47

Step	Description	Diagram
6.	Scroll to the next page and select Save to store the new time/date and	Save
	return to the Advanced Menu.	Return to Advanced Menu
7.	Select Sensor Calibrations	Advanced Settings
	Series Benger Canstations	Set Time / Date
		Sensor Calibrations
		Change Language
		Change Password
		Return to System Menu
8.	Select Calibrate Carrier Angle and	Sensor Calibration Menu
	then follow the instructions on the	Calibrate Carrier Angle
	screen to complete the calibration.	Calibrate Boom Angle
	Repeat for Calibrate Boom Angle and	Calibrate Boom Length
	Calibrate Boom Length.	Return to Advanced Menu

Table 18: Sensor Calibration

Appendix A: Attaching Display Connectors

The procedure below describes the correct method of attaching the cables to the screw lock connectors on the display.



If the M12 screw lock connectors on the display are over tightened, it will twist the connector pins attaching the connector to the PCB.

Step	Description	Diagram
1.	Connect the cable from the user control to the top 5 pin connector on the display. Connect the cable from the CCIM to the bottom 8 pin connector on the display.	9 5 Pin - User Control
2.	Line up the alignment hole on the cable connector with the alignment notch on the display connector.	

VER: 1706261613 41 of 47

Step	Description	Diagram
3.	Push the female connector from the cable into the male connector on the display.	
4.	Rotate the nut on the female connector by hand in a clockwise direction, until the tension on the nut starts to increase.	
5.	Push the cable in again and repeat steps 3 and 4 until the connector is secure.	

Table 19: Install Display Connector Procedure



The method to correctly secure the cable is to push-twist-push-twist until the connector is fully inserted and secure. This will minimise the twisting force applied to the connector.

Below is a picture of a damaged connector on the PCB inside the display. This damaged occurred because the connector was over tightened.




Illustration 4: Damaged Display Connector



Do not use any tools to tighten the connector.



Illustration 5: Do Not Use Tools To Tighten Connector



Do not over-tighten the nuts on the back of the display connectors. These nuts should only be hand tightened. If the nuts are overtightened it will damage the PCB inside the display.



Illustration 6: Do Not Over Tighten Nuts



Damage to the display connectors is not covered under warranty.

VER: 1706261613 44 of 47

Appendix B: Reattach Ferrites

If the clip-on ferrites on the displays are removed during installation, they will need to be reattached as shown in the procedure below.



If the ferrites are not reinstalled or attached in the specified location the Gen3-LMS kit will not meet the AS/NZS CISPR 22:2006 certification.

Step	Description	Diagram
1.	Attach the two clip-on ferrites at a location of 60 mm and 260 mm from the start of the connector to the start of the ferrite. Do this for both the CCIM and user control cables that plug into the display.	

Table 20: Reattach Ferrites Procedure

Indexes and Tables

Illustration Index

Illustration 1: Machine Boom	8
Illustration 2: Machine Chassis	
Illustration 3: Cable Reeler Mounting Position	13
Illustration 4: Damaged Display Connector	43
Illustration 5: Do Not Use Tools To Tighten Connector	43
Illustration 6: Do Not Over Tighten Nuts	44
Index of Tables	
Table 1: Component Installation Index.	6
Table 2: Cable Installation Index	7
Table 3: Cover removal	10
Table 4: Cable Reeler Installation	12
Table 5: Pressure Sensor Installation	15
Table 6: Compensation Pressure Sensor Installation	17
Table 7: Reverse Camera Installation	18
Table 8: Forward Camera Installation	19
Table 9: Signal Light Installation With Windshield Guard Bar	20
Table 10: Signal Light Installation Without Windshield Guard Bar	22
Table 11: Can Pressure Input Module (CPIM) Installation	24
Table 12: CCIM Installation	25
Table 13: External Cable Completion	26
Table 14: Dashboard Switches Installation	27
Table 15: Display Installation	28
Table 16: Machine Connections	33
Table 17: Finalisation	37
Table 18: Sensor Calibration	40
Table 19: Install Display Connector Procedure	42
Table 20: Reattach Ferrites Procedure	45

Equipment Safety Systems Pty. Ltd. ABN: 31 061 789 151 27 Cumberland Drive, Seaford 3198, Victoria, Australia

Tel: +61 3 8770 6555 Fax: +61 3 8770 6590 Web: www.eqss.com.au

VER: 1706261613