

eqss™ Gen-3 LMS Telehandler Load Management System

Installation Manual for MT1033 Mining 2022 Model





Do Not Swap Components between Gen3-LMS kits
When installing multiple Gen3-LMS kits, make sure the serial number on the sticker matches the serial number on the machine.

Failure To Follow Installation Manual Will Void Warranty

DO001460 VER: 2306221520 **EQSS**°

Documentation Conventions

The list below highlights important documentation conventions.



Text presented in this manner is intended to provide the user with some general information. The user should ensure information presented in this manner is clearly understood.



Text presented in this manner provides the user with information to assist in completion of the current procedure being explained.



Text presented in this manner indicates that a failure to follow directions could result in damage to equipment, loss of information, bodily harm, or loss of life.

DO001460 VER: 2306221520 CQSS 2 of 54

Important Information

Information contained in this publication regarding this device's applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that the application or our equipment meets with your specifications.

EQUIPMENT SAFETY SYSTEMS MAKE NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO, IT'S CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE.

Equipment Safety Systems disclaims all liability arising from this information and its use. Use of Equipment Safety Systems' products as critical components in life support systems is not authorised except with express written approval by Equipment Safety Systems. No licenses are conveyed, implicitly or otherwise, under any Equipment Safety Systems intellectual property rights.

DO001460 VER: 2306221520 CQSS 3 of 54

Table of Contents

Tools Required for Installation	6
Installation Index	7
Covers	11
Cable Reelers Installation	13
Pressure Sensor InstallationPressure ManifoldCompensation Pressure Sensors	15
Reverse Camera	18
SPU Cable Harness	20
Forward Camera	22
Stabiliser Cable Harness	24
Signal Light Installation	27
Joystick Cable Harness	29
Can Pressure Input Module (CPIM)	30
External Cable Completion	31
Display Installation	33
User Control	34
Can Cabin Interface Module (CCIM)	35
Cabin Loom	36
Finalisation	39
Set Time & Sensor Calibration	42
Schematics	45
Appendix A: Attaching Display Connectors	
Appendix B: Reattach Ferrites	

DO001460 VER: 2306221520 5 of 54

Tools Required for Installation

The tools required to perform the installation of the Gen3-LMS are listed below

- Pencil or Texta
- Drill
- · Drill bits
 - 3.3 mm
 - 4.5 mm
 - 。 5 mm
 - ∘ 6.25 mm
 - 。 6.8 mm
 - 。 8.5 mm
- Centre punch
- Tap T-Handle
- Taps
 - ∘ M6
 - o M7 x 0.75
 - o M8
- Drill and tap oil
- Metric Allen keys
- Phillips Head screw driver
- Spanners and sockets
 - 。 7 mm
 - 10 mm
 - 。 13 mm
- Locktite thread locker
- Side cutters
- Stanely knife
- Crimpers
- Wire strippers

DO001460 VER: 2306221520 EQSS 6 of 54

Installation Index

The components and cables of the Gen-3 Telehandler Load Management System are outline in the tables below. The following pages show where the components are installed and the cable routing.

See the appropriate manual section for a detailed installation description for each component.



Refer to this section for any component placement or cable routing issues

Item	Component Description
1	Standard Cable Reeler
2	Main Lift Cylinder Pressure Sensors
3	Compensation Cylinder Pressure Sensors
4	Can Pressure Input Module (CPIM)
5	Forward Camera
6	Light Tower
7	Rear Camera
8	Can Cabin Interface Module (CCIM)
9	Display Module
10	SPU Module
11	Stabiliser Connections
12	Joystick Connections (X43)

Table 1: Component Installation Index

DO001460 VER: 2306221520 PQSS 7 of 54

Colour	Cable Description
Yellow	Boom Cable
Dark Green	Main Cylinder Pressure Sensor Cables
Dark Blue	Compensation Cylinder Pressure Sensors Cables
Light Blue	Forward Camera Cable
Violet	Signal Light Cable
Aqua	Rear Camera Cable
Dark Purple	CCIM Cable
Light Green	Cutout Harness
Red	Display Cable
Orange	User Control Cable
Brown	Machine Input Harness
Dark Yellow	Stabiliser Harness

Table 2: Cable Installation Index

DO001460 VER: 2306221520 8 of 54



Illustration 1: Machine Boom




Illustration 2: Machine Chassis

Note: The old light tower is shown

DO001460 VER: 2306221520 EQSS 10 of 54

Covers

Remove the following covers before starting the installation

Step	Description	Diagram
1.	Remove the top and lower rear cover behind the boom.	
2.	Remove the side panel next to the cabin under the boom.	
3.	Remove the covers under the boom. Remove the covers over the stabiliser pressure manifolds	

DO001460 VER: 2306221520 EQSS 11 of 54

Step	Description	Diagram
4.	Inside the cabin remove the dashboard.	
5.	Remove the cover over the fluid containers	
6.	Remove the cover over the SPU behind the seat	

Table 3: Cover removal

DO001460 VER: 2306221520 12 of 54

Cable Reelers Installation

The standard cable reeler is used to measure the boom extension to determine the maximum lifting capacity. The ATR cable reeler is used to supply electrical power to the ID sensor for automatic tool selection.



A false N07 fault can occur if the boom jumps off the stow switch due to pressurising the hydraulic system and without operating the boom extension control. Ensure the stow switch arm is correctly adjusted to prevent this error.



When mounting the cable anchor for the standard cable reeler ensure it is mounted on the first extendable section not on the last section. If mounted on the last section the cable reeler will be damaged when the boom is extended.

Step	Description	Diagram
1.	Drill and tap 3 x M6 holes for the cable reeler in the location shown. Mount using the supplied bolts and washers.	
2.	Drill and tap an M8 hole for the cable anchor. Ensure the cable anchor is positioned so the cable runs in line with the boom. Mount the cable anchor and attach the cable. Drill and tap the M6 holes for the stow switch trigger bracket. Mount the stow switch trigger bracket using the supplied bolts and	

DO001460 VER: 2306221520 EQSS 13 of 54

Step	Description	Diagram
3.	Connect the supplied M12 10 metre cable (CB001027) into the cable reeler connection.	
4.	Run the cable from the cable reeler along the hydraulic pipes running down the boom, secure using cable ties every 150 mm to 200 mm. Cable tie to the flexible hydraulic hoses down to the chassis. Make sure the cables aren't pinched or stretched when the boom is raised or lowered. Run the remainder of the cables out the hole below the lift cylinder towards the rear of the machine and cable tie with the other cables during External Cable Completion on	

Table 4: Cable Reeler Installation



For further details on running the boom cables refer to the Installation Index on page 7

DO001460 VER: 2306221520 EQSS 14 of 54

Pressure Sensor Installation

The hydraulic pressure sensors are used to measure the lifting load of the telehandler.

Pressure Manifold



Failure to tighten the bolts to the correct torque on the pressure manifold may result in a pressure failure on the counterbalance valve causing an uncontrolled fall of the boom.

Step	Description	Diagram
1.	Raise the boom to approximately 40 degrees. Support and secure the boom using an A Frame or similar apparatus. It must support at least 2 tons. Apply the handbrake and insert chock under wheels. Remove the counterbalance valve on	
	Removing the counterbalance valve will release the hydraulic pressure which may result in a spray of oil. Secure the pressure manifold using the supplied 80 mm bolts and seals. Tighten the bolts for the manifold to 25 NM using a torque wrench. Start the machine, pressurise the boom and check for leaks.	

DO001460 VER: 2306221520 EQSS 15 of 54

Step	Description	Diagram
2.	Connect the supplied M12 4 metre cables (CB001026) into each of the pressure sensors. Add both cables to 3 m of snake tube. Cable tie to the flexible hydraulic hoses connected to the main lift cylinder. Make sure the cable isn't pinched or stretched when the boom is raised or lowered. Run the remainder of the cable out the hole above the rear axle under the lift cylinder towards the rear of the machine and cable tie with the other cables during External Cable Completion on page 31.	
	Ensure the pressure sensors and cables do not collide with the boom and chassis structures and the cables do not stretch or pinch when the boom is raised and lowered.	

Table 5: Pressure Manifold Installation



For further details on running the pressure sensor cables refer to the Installation Index on page 7

DO001460 VER: 2306221520

Compensation Pressure Sensors

Step	Description	Diagram
1.	Install the pressure sensors with the tee connections into the head and rod of the compensation cylinder.	C Rod
	Start the machine, pressurise the boom and check for leaks.	
	Connect the supplied M12 4 metre cables (CB001026) into each of the pressure sensors.	C Head
	Add both cables to 3 m of snake tube.	View from behind the cabin towards the rear of the machine
	Run the remainder of the cable out the hole above the rear axle under the lift cylinder towards the rear of the machine and cable tie with the other cables during External Cable Completion on page 31.	
	Ensure the pressure sensors and cables do not collide with the boom and chassis structures and the cables do not stretch or pinch when the boom is raised and lowered.	

Table 6: Compensation Pressure Sensor Installation



For further details on running the pressure sensor cables refer to the Installation Index on page 7

DO001460 VER: 2306221520 PG 54

Reverse Camera

The rear camera video is displayed on the screen when the machine is in reverse gear to allow the operator to see behind the telehandler while reversing.



Do not disconnect the camera power connection while the system is operating as this can damage the fuse.

Step	Description	Diagram
1.	Drill a 31mm hole in the location shown. Insert the camera through the hole and adjust the angle using the alignment washers.	MANITOU
2.	Connect the camera power and signal connectors to the supplied 5m camera cable (CB001032). Note; The white connector is not used. Secure the camera cable using a single cable tie to maintain the connector location. Run the remainder of the cable towards the cabin and cable tie with the other cables during External Cable Completion on page 31.	

Table 7: Reverse Camera Installation



The camera's viewing angle may need to be adjusted once the system is installed and the display is operational.

DO001460 VER: 2306221520 PQSS 18 of 54



Once the cable has secured with a cable tie disconnect the cable to remove the rear cover until the installation is finalised



For further details on running the camera cable refer to the Installation Index on page 7

DO001460 VER: 2306221520 PQSS 19 of 54

SPU Cable Harness



Isolate the main battery before connecting into the machine

Step	Description	Diagram
1.	Push the snake tube containing the terminal for the SPU connector cutout signal from under the boom through the hole into the cabin with the other snake tube cables for the SPU. Cable tie the snake tube into the existing tube going into the seal.	
	existing tube going into the Scal.	
2.	Remove the connectors from the SPU and insert the cutout terminal into B21 . Note: If there is already a terminal in	
	this position splice the cutout signal into this terminal wire. Cable tie to the SPU snake tube.	
3.	Run the snake tube and cables towards the cabin and cable tie with the other cables during External Cable Completion on page 31.	

Table 8: SPU Cable Harness Installation

DO001460 VER: 2306221520



For further details on running the spu cable harness refer to the Installation Index on page 7

DO001460 VER: 2306221520 EQSS 21 of 54

Forward Camera

The forward camera video is displayed on the screen when the machine is in forward gear to allow the operator to see past the boom to obstructions that would damage the right front tyre.



Do not disconnect the camera power connection while the system is operating as this can damage the fuse.

Step	Description	Diagram
1.	Mount the camera to the side mirror using the p-clips as shown. Secure using two M6 nuts.	
2.	Connect the camera power and signal connectors to the supplied 5m camera cable (CB001032). Note; The white connector is not used. Run the cable along the same path as the headlight cable, run it through the headlight post, then under the chassis to the side of the cabin. Cable tie to the headlight cable every 150 mm to 200 mm. Complete the cable installation during External Cable Completion on page 31.	

Table 9: Forward Camera Installation

DO001460 VER: 2306221520



The camera's viewing angle may need to be adjusted once the system is installed and the display is operational.



For further details on running the camera cable refer to the Installation Index on page 7

DO001460 VER: 2306221520 CQSS 23 of 54

Stabiliser Cable Harness



The pressure switches don't come with the MT1033 as standard and will need to be order from Maniton standard and will need to be order from Manitou.

Step	Description	Diagram
1.	Install the supplied manifold block between the existing manifold block and the cylinder for each stabiliser.	

DO001460 VER: 2306221520

Step	Description	Diagram
2.	Install the Stabiliser Hydraulic Guard Plate on both sides of the stabiliser as shown in the image. Secure using the supplied bolts and ensure the O-rings are in place.	
3.	Connect the 3 pin connector labelled left stabiliser from the stabiliser harness into the left stabiliser pressure switch. Connect the 3 pin connector labelled right stabiliser from the stabiliser harness into the right stabiliser pressure switch. Cable tie to the existing snake tube.	
	Run the remainder of the cable towards the cabin and cable tie with the front camera cable harness during External Cable Completion on page 31.	

DO001460 VER: 2306221520 CQSS 25 of 54



For further details on running the stabiliser cable harness refer to the Installation Index on page 7

DO001460 VER: 2306221520



Signal Light Installation

The signal light warns other workers when the telehandler is lifting loads close to it's maximum capacity.



Ensure the power supply voltage is greater than 13.5V otherwise the signal light may not illuminate correctly.

Step	Description	Diagram
1.	Mount the signal light on the top of the roof past the roof window towards the cabin door.	
2.	Run the cable towards the boom side of the roof and push through the hole near the window wiper. Note: It might be necessary to cut a hole in the plastic roof cover to fit the cable. Run the cable under the cover towards the rear corner.	

DO001460 VER: 2306221520 C7 of 54

Step	Description	Diagram
3.	Run the cable along the pipes under the cover towards the chassis.	
	Cable tie with the other cables during External Cable Completion on page 31.	

Table 11: Signal Light Installation

DO001460 VER: 2306221520 28 of 54

Joystick Cable Harness



Isolate the main battery before connecting into the machine wiring

Step	Description	Diagram
1.	Locate the connectors under the boom next to the cabin, that connect into the joystick.	O
	Connect the 12 pin tee connector into X67.	
	Run the cable towards the cabin and cable tie with the other cables during External Cable Completion on page 31.	

Table 12: Joystick Cable Harness Installation



For further details on running the joystick cable harness refer to the Installation Index on page 7

DO001460 VER: 2306221520 PQSS 29 of 54

Can Pressure Input Module (CPIM)

The CPIM is responsible for processing the information sent from the pressure sensors.



Accidentally swapping the pressure sensor connections will not damage system and can be determined if the display is showing a negative load.



Do not plug the pressure sensor cable into the far right side boom cable. This will damage the system.

Step	Description	Diagram
1.	Drill and tap two M8 holes for the CPIM bracket in the chassis rear panel. Mount using the supplied M8 x 12mm bolts and washers.	
2.	Connect the cables for the pressure sensors and boom cable to the CPIM according to the picture shown. Note: The CCIM cable will be installed during External Cable Completion on page 31.	MAIN ROD MAIN HEAD COMP ROD COMP ROD COMP ROD COMP ROD CCIM BOOM

Table 13: Can Pressure Input Module (CPIM) Installation

DO001460 VER: 2306221520 CQSS 30 of 54

External Cable Completion

All external cabling is completed in this step.

Step	Description	Diagram
1.	Drill and install the supplied P-Clips. Use these P-Clips as an anchor for the cable ties to fasten the excess cable for the pressure sensor, and boom cable.	
2.	Connect the supplied M12 4 metre for the CCIM. Run the cable out the hole under the lift cylinder.	MAIN ROD MAIN HEAD COMP ROD COMP ROD COMP ROD COMP ROD CCIM BOOM
3.	Cable tie the CCIM, signal light, rear camera, cutout and machine input harnesses together along the side to the front of the cabin.	

DO001460 VER: 2306221520 CQSS 31 of 54

Step	Description	Diagram
4.	Run the CCIM, signal light, cutout harness, stabiliser cable harness and camera cables up through the hole into the cabin under the dashboard. Note: Pull the entire length of cable through into the cabin, excess cable will be stored under the dashboard cover in the cabin.	

Table 14: External Cable Completion



For further details on running the cables refer to the Installation Index on page 7

DO001460 VER: 2306221520 EQSS 32 of 54

Display Installation

The display shows the current safety status of the telehandler.

Step	Description	Diagram
1.	Attach the display bracket to the level indicator in the top right corner using the supplied bolts and nuts. Attach the display to the bracket and tighten the locking nut in the correct position.	

Table 15: Display Installation



Adjust the display bracket for optimal viewing angle once the display is powered



If the M12 screw lock connectors on the display are over tightened it will twist the connector pins attaching the connector to the PCB. See Appendix A: Attaching Display Connectors on page 48 for the correct method of attaching to the display connectors.



If the clip-on ferrites were removed from the CCIM and user control cables. See Appendix B: Reattach Ferrites and page 52 for the correct reattachment position.

D0001460 VER: 2306221520 EQSS 33 of 54

User Control

The user control consists of a 5 button switch mounted in the dashboard.

Step	Description	Diagram
1.	Drill a 39 mm hole into the cover in front of the joystick and install the user control dial.	
	Note: Be careful while drilling not to damage the hydraulic controls positioned under the cover.	
2.	Run the cable through under the dashboard with the other cables.	

Table 16: User Input Control Installation



If the M12 screw lock connectors on the display are over tightened it will twist the connector pins attaching the connector to the PCB. See Appendix A: Attaching Display Connectors on page 48 for the correct method of attaching to the display connectors.

DO001460 VER: 2306221520 CQSS 34 of 54

Can Cabin Interface Module (CCIM)

The CCIM connects the system into the machine electronics.

Step	Description	Diagram
1.	Position the backup battery underneath the dashboard as shown and secure using double sided velcro tape.	
2.	Position the CCIM next to the brake fluid container as shown and secure using double sided velcro tape. Remove the CCIM from the velcro to allow the connections to be completed. Reattach to the velcro in the section Finalisation on page 39.	

Table 17: CCIM Installation

DO001460 VER: 2306221520 CQSS 35 of 54

Cabin Loom

The cabin loom connects the CCIM to the machine connections and the other modules of the system.



Isolate the main battery before connecting into the machine wiring



Do not disconnect the camera power connection while the system is operating as this can damage the fuse.

Step	Description	Diagram
1.	Connect the CCIM and signal light cables to the M12 connectors on the CCIM. Note: It doesn't matter which of the M12 connectors the CCIM and signal light cables are plugged into.	Carnaria / Power 1/0
2.	Connect the Power/Camera and IO Harnesses to the bulkhead connectors on the CCIM.	PONEF CENTER MANNETS

DO001460 VER: 2306221520 CQSS 36 of 54

Step	Description	Diagram
3.	Connect the camera power and signal cables to the cabin loom. Note: The white connector is not used.	
4.	Connect the 4 pin female connector from the machine input harness, the 6 pin female connector from the cutout cable harness and the 2 pin and 12 pin connectors from the stabiliser harness to the cabin loom connectors. Note: If stabilisers are not fitted leave the 2 and 12 pin disconnected	
5.	Run the 8 pin cable from the CCIM and 5 pin cable from the user control through the gap between the window and the dashboard. Run both cables through snake tube and attach to the connectors to the back of the display.	
6.	Place cable tie points on the side of the window. Cable tie the snake tube to the cable tie points. Connect the cables to the display. Do not over-tighten the connectors.	

DO001460 VER: 2306221520 37 of 54



If the M12 screw lock connectors on the display are over tightened it will twist the connector pins attaching the connector to the PCB. See Appendix A: Attaching Display Connectors on page 48 for the correct method of attaching to the display connectors.



If the clip-on ferrites were removed from the CCIM and user control cables. See Appendix B: Reattach Ferrites and page 52 for the correct reattachment position.

DO001460 VER: 2306221520

Finalisation

This section will complete the final power connections to power the system and finish any additional items.

Step	Description	Diagram
1.	Cut wire 478 into terminal 1 of the switch. Join the yellow wire from the machine input harness to side of wire 478 leading towards the switch. Join the violet wire from the machine input harness to the other side of wire 478 leading towards the electronics.	
2.	Locate the power connector for the radio. Connect the radio power tee connectors from the radio power harness to the power connector for the radio. Connect the 3 pin connector to the cabin loom connector.	
3.	Connect the spade lug on the black wire to the negative (black) battery terminal. Connect the spade lug on the blue wire to the positive (red) battery terminal.	

DO001460 VER: 2306221520 PQSS 39 of 54

Step	Description	Diagram
4.	Attach the CCIM to the velcro strips installed earlier.	
5.	Coil up the extra cables and store underneath the dashboard cover. Reconnect the main battery from the isolation switch. Turn the machine onto first stage /accessories and ensure the system is activated.	
6.	Adjust the display bracket for optimal viewing Set the machine into forward gear to activate the forward camera. Adjust the forward camera so the front right wheel is visible. Set the machine into reverse gear to activate the reverse camera. Adjust the reverse camera so the video is level.	egtes Gent Life
7.	Operate the boom movement controls to test if a false N07 fault occurs. If a N07 fault does occur, adjust the arm on the stow switch forwards towards the stow switch trigger. Note: The actual switch arm orientation may differ from the picture.	

DO001460 VER: 2306221520 40 of 54

Step	Description	Diagram
8.	Perform a final check on all the cabling and sensors.	BANGA
	Replace all the covers	

Table 19: Finalisation



Make sure to update the machine ECU software for Australian configuration using the Manitou pad.



Complete the system checklist once installation has been completed.

Set Time & Sensor Calibration

Once the installation is complete, the time will need to be set and the sensors will require calibration.



A sensor calibration must be performed once the cable reeler and CPIM have been mounted. If the cable reeler or CPIM have been moved/repositioned a recalibration must be performed

Step	Description	Diagram
1.	Press Enter on the user control dial	Main Menu
	to enter the menu system. Press the arrow buttons to select	Attachment Selection Menu
	System Menu. Press Enter to select the menu.	System Menu
		Exit Menu
2.	Select Advanced Menu	System Menu
		Volume / Brightness
		Status Menu
		Diagnostics Menu
		System Tests
		Advanced Menu
		Return to Main Menu

Step	Description	Diagram
3.	Enter the password	Enter Password
	(Default Password: 2-8-4)	Number 1 2
		Number 2 8
		Number 3 4
		Submit Password
		Return to System Menu
4.	Select Set Time / Date	Advanced Settings
7.	Select Set Time / Date	Set Time / Date
		Sensor Calibrations
		Change Language
		Change Password
		Return to System Menu
5.	Enter the correct time and date for	Set Time / Date
	your area.	Hour 15
	Press the arrow keys to select a	Minute 54
	time/date parameter	Day 10
	Press Enter and the parameter will change to red, press the arrow keys to change the value and then press the Enter key to store the value.	Month 2
		Year 2016
		Region Melbourne
	Note: The hour parameter is in 24 hour clock	
	Repeat for the rest of the time values	


DO001460 VER: 2306221520 43 of 54

Step	Description	Diagram
6.	Scroll to the next page and select Save to store the new time/date and	Save
	return to the Advanced Menu.	Return to Advanced Menu
7.	Select Sensor Calibrations	Advanced Settings Set Time / Date Sensor Calibrations
		Change Language
		Change Password
		Return to System Menu
8.	Select Calibrate Carrier Angle and then follow the instructions on the screen to complete the calibration.	Sensor Calibration Menu Calibrate Carrier Angle
	Repeat for Calibrate Boom Angle and Calibrate Boom Length.	Calibrate Boom Angle
		Calibrate Boom Length
		Return to Advanced Menu


Table 20: Sensor Calibration


DO001460 VER: 2306221520 44 of 54

Schematics



DO001460 VER: 2306221520 45 of 54





Appendix A: Attaching Display Connectors

The procedure below describes the correct method of attaching the cables to the screw lock connectors on the display.



If the M12 screw lock connectors on the display are over tightened, it will twist the connector pins attaching the connector to the PCB.

Step	Description	Diagram
1.	Connect the cable from the user control to the top 5 pin connector on the display. Connect the cable from the CCIM to the bottom 8 pin connector on the display.	9 5 Pin - User Control 8 Pin - CCIM
2.	Line up the alignment hole on the cable connector with the alignment notch on the display connector.	

DO001460 VER: 2306221520 48 of 54

Step	Description	Diagram
3.	Push the female connector from the cable into the male connector on the display.	
4.	Rotate the nut on the female connector by hand in a clockwise direction, until the tension on the nut starts to increase.	
5.	Push the cable in again and repeat steps 3 and 4 until the connector is secure.	

Table 21: Install Display Connector Procedure



The method to correctly secure the cable is to push-twist-push-twist until the connector is fully inserted and secure. This will minimise the twisting force applied to the connector.

Below is a picture of a damaged connector on the PCB inside the display. This damaged occurred because the connector was over tightened.

DO001460 VER: 2306221520 49 of 54




Illustration 3: Damaged Display Connector



Do not use any tools to tighten the connector.



Illustration 4: Do Not Use Tools To Tighten Connector

DO001460 VER: 2306221520 EQSS 50 of 54



Do not over-tighten the nuts on the back of the display connectors. These nuts should only be hand tightened. If the nuts are overtightened it will damage the PCB inside the display.



Illustration 5: Do Not Over Tighten Nuts



Damage to the display connectors is not covered under warranty.

DO001460 VER: 2306221520 51 of 54

Appendix B: Reattach Ferrites

If the clip-on ferrites on the displays are removed during installation, they will need to be reattached as shown in the procedure below.



If the ferrites are not reinstalled or attached in the specified location the Gen3-LMS kit will not meet the AS/NZS CISPR 22:2006 certification.

Step	Description	Diagram
1.	Attach the two clip-on ferrites at a location of 60 mm and 260 mm from the start of the connector to the start of the ferrite. Do this for both the CCIM and user control cables that plug into the display.	

Table 22: Reattach Ferrites Procedure

DO001460 VER: 2306221520 EQSS 52 of 54

Indexes and Tables

Illustration Index

Illustration 1: Machine Boom	
Illustration 2: Machine Chassis.	
Illustration 3: Damaged Display Connector	50
Illustration 4: Do Not Use Tools To Tighten Connector	50
Illustration 5: Do Not Over Tighten Nuts	51
Index of Tables	
Table 1: Component Installation Index	7
Table 2: Cable Installation Index	8
Table 3: Cover removal	12
Table 4: Cable Reeler Installation	14
Table 5: Pressure Manifold Installation	16
Table 6: Compensation Pressure Sensor Installation	17
Table 7: Reverse Camera Installation	18
Table 8: SPU Cable Harness Installation	20
Table 9: Forward Camera Installation	
Table 10: Stabiliser Cable Harness Installation	
Table 11: Signal Light Installation	
Table 12: Joystick Cable Harness Installation	
Table 13: Can Pressure Input Module (CPIM) Installation	
Table 14: External Cable Completion	
Table 15: Display Installation	
Table 16: User Input Control Installation	
Table 17: CCIM Installation	
Table 18: Cabin Loom Installation	
Table 19: Finalisation	
Table 20: Sensor Calibration	
Table 21: Install Display Connector Procedure	
Table 22: Reattach Ferrites Procedure	52

Equipment Safety Systems Pty. Ltd. ABN: 31 061 789 151 75 Naxos Way, Keysborough 3173, Victoria, Australia

Tel: +61 3 8770 6555 Fax: +61 3 8770 6590 Web: <u>www.eqss.com.au</u>

DO001460 VER: 2306221520 EQSS 54 of 54